DUMONT BOROUGH HALL

Prepared By: County of Bergen
Department of Health Services
Melissa Johnson, MS, Industrial Hygienist



Leader from gutter-old drain clogged. Downspout leader pulled away from building to keep water away.

Exterior vines growing into the Building

Exterior wall by Police Captain's office
and Vault area:
Needs new bricks and
painting-causes water to enter building

Exterior ground level by Vault area causing water problems inside.

Steps falling apart on exterior of building.

Exterior bricks damaged:
When it rains water enters the building.

Exterior door beyond repair-
rotted away.